

Removed at request of company


Removed at request of company

Senior Citizens


Center Photo Key Plan
 Key numbers match work item numbers
 04-24-09

58 Various External and Internal Views of doors and windows

Keyed Numbers: Refer to photos taken of damaged building and used to illustrate line items in repairs estimate.



58 Various External and Internal Views of doors and windows



Removed at request of company

Removed at request of company
Multi-Service

Removed at request of company

STREET

Keyed Numbers: Refer to photos taken of damaged building and used to illustrate line items in repairs estimate.

Center Photo Key Plan
Key numbers match work item numbers
04-24-09

4

4

A12

34

4

3a

34

23c

41

A15

4

A30

39/A3

13/16/A25/A27/A28/A31

8

8

32/45

11

7

12/A15

8

A15

A2

28/A11/A23

6

38 (on roof)

20, 21

5/A15

23a,b

A5

37(on roof)

3b

A5

A12

A12

A12

Keyed Numbers: Refer to photos taken of damaged building and used to illustrate line items in repairs estimate.

Removed at request of company


Removed at request of company

Gymnasium

Photo Key Plan

Key numbers match work item num
04-24-09

Removed
at request
of
company



Removed
at request
of
company

Removed
at request
of
company

Removed
at request
of
company